

August 2017

## ENERGY SAFETY WARNING

# Non-compliant and unsafe TPS Cable has been supplied in New Zealand

The 2 core +PE cable sold in 1.5 mm<sup>2</sup> and 2.5 mm<sup>2</sup> is marked 'EESS 150102-0'.

If seen for sale, at worksites or installed, anywhere in the course of your work, please immediately call Energy Safety on 0800 030 040.

Such cable installed will have to be removed and replaced. Do not issue a CoC for any installation containing this cable.

